Corrals Nous, 77
Pol. Industrial Can Roqueta
08202 Sabadell
(Barcelona - Spain)

Tel. 93 729 27 00 Fax 93 729 30 73 www.ftemaximal.com



-mediaMAX MINI HD-What's new in this version / Change Log

Versión 1.56

- 1. Added new option into the menu Setup>System multiwindow mode to enabled or disable the multi windows. This option is only available in mini S2C2T2 HD.
- 2. Added in the list of options FAV button the multiwindows mode. This option is only available in mini S2C2T2 HD.
- 3. Fixed error in the quality bar in DVB- in the mini S2C2T2HD

Versión 1.54

- 1. Added new option auto in band high and low into SATCR menu. This option is similar to tone 22KHz auto.
- 2. Improvement in the power measurement of the DVB-C in the mini S2C2T2HD
- 3. Improvement in the BER(b) in DVB-T.
- 4. Improvement in the support of some model of SATCR switch
- 5. Added CAS/ID option in the Transmodulator tool.
- 6. Fixed a problem in the datalogger when the audio was FM radio
- 7. Fixed error 0505 y 0508 in transmodulators tools, while was configured the output channel settings in a transmodulator in DVB-C, with a mini S2T HD

Versión 1.52

- 1. First version of mini S2C2T2 HD.
- 2. The frequency display in the preview datalogger measurement is the IF Slot.
- 3. Fixed a problem in some case selecting the standard in the external video.
- 4. Added screenshot in the list of FAV button.

Versión 1.46

1. Fixed a problem the meter can not lock DVB-C signal in same cases.

Version 1.45

- 1. Added in display the name of the satellite or the name of the network in spectrum mode, navigating by frequency.
- 2. Improvement in transmodulator tool. Now it is possible to see more than 64 input services in a TP.
- 3. Fixed spectrum display problem while in navigation by frequency after using a specific program.
- 4. Fixed some painting errors.
- 5. Improvement in the method to find the SATCR pilot. Now appear more information.
- 6. Fixed error in satellite finder.

Version 1.39

- 1. Fixed analogical audio problem.
- 2. Fixed buzzer problem.
- 3. Added TS capture function.
- 4. Improvement in DVB-T band scan.
- 5. Removed PRO200 tool.
- 6. Removed key beep in system setup.
- 7. Fixed Problem in the HDMI output when the meter returns from standby mode.
- 8. Fixed meter hang for about 35 seconds while changing satellite program.
- 9. Fixed some translations in English.
- 10. Fixed some translations in French.
- 11. Improvement in maximum hold value displayed.
- 12. Fixed some repainting problems.
- 13. Improvement in transmodulators tool.
- 14. Improvement in DVB-T tool.

Version 1.23

- 1. Fixed a problem with some USB flash drive detection.
- 2. Fixed a problem with Wake Up function.

Version 1.22

- 1. Fixed a problem of rebooting in the satellite identification tool.
- 2. Fixed a hang in audio menu.
- 3. Fixed a translation mistake in information window.

Corrals Nous, 77 Pol. Industrial Can Roqueta 08202 Sabadell (Barcelona - Spain) Tel. 93 729 27 00 Fax 93 729 30 73 www.ftemaximal.com

Version 1.21

- 1. Fixed the boot version in datalogger. It always was 0.00.
- 2. Now the field meter shows information after making a factory default reset.
- 3. Transmodulator tool: fixed a hang with MTW 310 modules.
- 4. Fixed a problem in datalogger trying to get a digital signal in DVB-T and DVB-C.
- 5. The bootloader is upgraded to version 1.1.2.
- 6. Now the kernel version is displayed in information window.
- 7. Fixed a translation mistake in information window.

Version 1.20

- 1. Fixed a redraw problem in mode MAX Hold
- 2. Fixed error of measure quality in the Monitor mode
- 3. Fixed problem in LNB short circuit protection system
- 4. Fixed the filter value in the Datalogger
- 5. Fixed an repainting error in menu grid
- 6. Fixed hang when restoring a backup
- 7. Now AAC audio is supported.
- 8. The shutting down message is translated
- 9. Now in the information window IP address only if Ethernet input is connected
- 10. Changed MO by Mbytes in the Information window when the language is not French
- 11. Some translations have been updated
- 12. PRO 200 Tool is removed because it is not supported in HD meter.

Version 1.17

1. First version for the MediaMAX MINI HD S2T / MediaMAX MINI HD S2CT.